Erratum to “The influence of joints on friction induced vibration in brake squeal” [J. Sound Vib. 340 (2014) 239–252]

Sebastian Kruse^{a,b,*}, Merten Tiedemann^b, Bernhard Zeumer^c, Pascal Reuss^c,
Hartmut Hetzler^d, Norbert Hoffmann^{b,e}

^a Audi AG, Development Foundation Brake, 85045 Ingolstadt, Germany

^b Hamburg University of Technology, Dynamics Group, 21073 Hamburg, Germany

^c University of Stuttgart, Institute of Applied and Experimental Mechanics, 70569 Stuttgart, Germany

^d University of Kassel, Engineering Dynamics Group, Institute for Mechanics, 34125 Kassel, Germany

^e Imperial College London, Department of Mechanical Engineering, London SW7 2AZ, United Kingdom

The publisher regrets to inform that two errors occurred in the printed version of the above listed article. Fig. 5 appeared in the final printed version in the following format:

Fig. 5. Transition from supercritical to subcritical Hopf-bifurcation triggered by k_{nl} . Stable equilibrium and period solutions are plotted as solid lines, unstable solutions as dashed lines.

DOI of original article: <http://dx.doi.org/10.1016/j.jsv.2014.11.016>

* Corresponding author at: Audi AG, Development Foundation Brake, 85045 Ingolstadt, Germany.

E-mail address: sebastian.kruse@audi.de (S. Kruse).

<http://dx.doi.org/10.1016/j.jsv.2015.04.029>

0022-460X/© 2015 Elsevier Ltd. All rights reserved.

The correct display of the figure is below, with the correct symbols circled:

Fig. 7a contained an error in the labelling of the horizontal-axis, which appeared in the printed article as k_z , when the label should in fact have been k_x .

The correct label is highlighted below:

Please note that the online version is now correct. The publisher would like to apologise for any inconvenience caused.